

Under Review Notification

Raised By: MICHAEL LEE

Product #: D139-1019

Date: 16.12.08

Product Name: REPLACEMENT WINDOW KITS

Part Number (D-Part and 9-Digit)	Drawing/Document & Current Affected Revision	"Y" or "N" Required for Each Part							Reserved ECN Log Number	Instructions Relevant to Each Part
		HOLD SHIPMENT	Red Tag/Quarantine Stock	Advise Customers	Stop Production	Re-Work Stock	PP Under Review	Product Specifications Under Review		
D5381-1	D5381 REV. A	Y	Y	N	Y	Y	Y	N	16-685	SEE BELOW
D5381-3	D5381 REV. A	Y	Y	N	Y	N	Y	N	16-685	SEE BELOW
D139-1019-011/-012	IIN-D139-1019	Y	Y	N	Y	N	Y	Y	16-685	SEE BELOW

Description of Issue:

CUSTOMER REPORTS THAT THE D5381-1 WINDOW BUSHINGS MAY BE TOO LONG AND THAT THE D5381-3 GROMMETS ARE "SPLITTING/CRACKING" WITH DAYS OF BEING INSTALLED ON THE AIRCRAFT. REF. NCR 16-6138

PLEASE QUARANTINE ALL STOCK OF D5381-1/-3

D5381-1 MAY BE REWORKED, ENGINEERING WILL ADVISE PRODUCTION

Distribution:

VP Operations	Chief Engineer	Production Engineers	Purchasing Manager
Director of Operations	Engineering Project Managers	Planning Manager	
Director Quality Assurance	Engineering Clerk	Program Manager	
Director of Engineering	Customer Support Manager	Technical Support	